

BARLOWS

Barlows (UK) Ltd Fire & Security

Clifford House, Hampton Heath Industrial Estate, Malpas, Cheshire

Telephone: 03303110999 Fax: 01948 820232

www.barlowsuk.co.uk Email: fireandsecurity@barlowsuk.co.uk



Job Number	M0708663	Fire Alarm Inspection & Servicing Certificate
-------------------	----------	--

Customer	Tarporley Community Centre		
Address	High Street		
Postcode	CW6 0AY		
Site	Tarporley Community Centre		
Address	High Street Tarporley Cheshire		
Postcode	CW6 0AY		
Type of Service	Periodic	Frequency of Visits	Six Monthly
Percentage tested	100%%	Extent of system covered by this certificate	All areas

Variations from the recommendation of clause 45 of BS5839-1:2013 for periodic or annual inspection and test (as applicable)

None		
------	--	--

Relevant details of the work carried out and faults identified have been entered in the system logbook	Yes/No	No
---	---------------	----

The following work/action is considered necessary

None		
------	--	--

Details of Inspection & Testing

Make of panel	C-tec	Number of Sounders	9
Model Number	Cfp	Number of Call Points	9
Protocol	Open	Battery Size	3AH
Number of Detectors	25	Battery Quantity	2
No. of Manual Call Points	9	Battery Install Month/Yr	02/2018
Is there a correct and up to date Zone plan adjacent to the fire alarm Panel?			No

The following items were found to be defective and were resolved at the point of service:

None		
------	--	--

Arrival Time / Date	Departure Time /Date
13/08/2018 8:25	13/08/2018 11:29

Engineer	Chris Slater
-----------------	--------------

I/we being the competent person(s) responsible for the servicing of the fire detection and fire alarm system, particulars of which are set out above, CERTIFY that the said work for which I/we have been responsible complies to the best of my/our knowledge and belief with the recommendations of Clause 45 of BS5839-1:2013

Accepted, for and behalf of the user, by the Responsible Person (RP). I understand that the system is operating as designed. I understand that if any items were shown to be defective, the fire alarm system may not comply with BS 5839 part 1

Customer	Tony yeates
-----------------	-------------