

# BARLOWS

## Barlows (UK) Ltd Fire & Security

Clifford House, Hampton Heath Industrial Estate, Malpas, Cheshire

Telephone: 03303110999 Fax: 01948 820232

www.barlowsuk.co.uk Email: fireandsecurity@barlowsuk.co.uk



<b>Job Number</b>	M0706786	<b>Fire Alarm Inspection &amp; Servicing Certificate</b>
-------------------	----------	--

<b>Customer</b>	Tarpoley Community Centre		
<b>Address</b>	High Street		
<b>Postcode</b>	CW6 0AY		
<b>Site</b>	Tarpoley Community Centre		
<b>Address</b>	High Street Tarpoley Cheshire		
<b>Postcode</b>	CW6 0AY		
<b>Type of Service</b>	Periodic	<b>Frequency of Visits</b>	Six Monthly
<b>Percentage tested</b>	50%%	<b>Extent of system covered by this certificate</b>	All zones

**Variations from the recommendation of clause 45 of BS5839-1:2013 for periodic or annual inspection and test (as applicable)**

None		
------	--	--

<b>Relevant details of the work carried out and faults identified have been entered in the system logbook</b>	<b>Yes/No</b>	No
---	---------------	----

**The following work/action is considered necessary**

None		
------	--	--

**Details of Inspection & Testing**

<b>Make of panel</b>	C-tec	<b>Number of Sounders</b>	4
<b>Model Number</b>	CFP	<b>Number of Call Points</b>	8
<b>Protocol</b>	Open	<b>Battery Size</b>	3AH
<b>Number of Detectors</b>	15	<b>Battery Quantity</b>	2
<b>No. of Manual Call Points</b>	8	<b>Battery Install Month/Yr</b>	02/2018
<b>Is there a correct and up to date Zone plan adjacent to the fire alarm Panel?</b>		<del>No</del> YES	

**The following items were found to be defective and were resolved at the point of service:**

Replaced panel batteries as they were over 3 years old		
--	--	--

<b>Arrival Time / Date</b>	<b>Departure Time /Date</b>
05/02/2018 13:30	05/02/2018 16:34

	<b>Engineer</b>	Chris Slater
I/we being the competent person(s) responsible for the servicing of the fire detection and fire alarm system, particulars of which are set out above, CERTIFY that the said work for which I/we have been responsible complies to the best of my/our knowledge and belief with the recommendations of Clause 45 of BS5839-1:2013		
	<b>Customer</b>	Tony
Accepted, for and behalf of the user, by the Responsible Person (RP). I understand that the system is operating as designed. I understand that if any items were shown to be defective, the fire alarm system may not comply with BS 5839 part 1		