

Fire Extinguisher Testing Certificate

Customer Details						
Customer	Tarpорley & District Community Centre			Job Ref	7A129952	
Customer Address	High Street Tarpорley CW6 0AY			Date	15/08/2023	
Extinguisher Checklist						
Asset no	Asset Type	Extinguisher location	Installation date	Tested? Y/N	Passed? Y/N	Replaced? Y/N
1	2kg Co2	Room on the left by entrance	15-08-2023 12:51	Yes	Yes	No
2	6L Foam	Entrance	15-08-2023 12:52	Yes	Yes	No
3	2kg Co2	Main kitchen	15-08-2023 12:53	Yes	Yes	No
4	Fire Blanket	Main kitchen	15-08-2019 12:54	Yes	Yes	No
5	6L Foam	Hall entrance	15-08-2023 12:55	Yes	Yes	No
6	6L Foam	Hall fire exit	15-08-2020 12:57	Yes	Yes	No
7	6L Foam	Hall fire exit	15-08-2018 12:59	No	No	No
8	5kg Co2	Stage	15-08-2016 13:03	Yes	Yes	No
9	6L Foam	By far kitchen	15-08-2019 13:06	Yes	Yes	No
10	2kg Co2	The craven room kitchen	15-08-2023 14:01	Yes	Yes	No
11	2kg Co2	Craven room kitchen	15-08-2014 14:03	Yes	Yes	No
12	2kg Co2	Car park boiler room	15-08-2019 15:10	Yes	Yes	No
13	6L Foam	The craven room	15-08-2019 15:12	Yes	Yes	No
14	2kg Co2	Hall by AV equipment	15-08-2023 15:51	Yes	Yes	No
The following items were found to be required for the system to comply with BS5306-3:2009		1 x 6l foam expired in hall				

Stock Usage			
Signing off			
Time Arrived	12:21	Time Departed	15:53
Technician	Bruce Shaw	Signature	/
Customer	Bruce Shaw	Signature	